# United States Environmental Protection Agency Region V POLLUTION REPORT

EPA Region 5 Records Ctr.

Date: Friday, November 21, 2008

From: Jon Gulch, On-Scene Coordinator

To: David Chung, U.S. EPA

Linda Nachowicz, U.S. EPA Michael Chezik, DOI

Debbie Keating, U.S. EPA

Afif Marouf, U.S. EPA Mick Hans, U.S. EPA Kevin Clouse, Ohio EPA

Timothy Murphy, City of Toledo

Jason El-Zein, U.S. EPA Mark Durno, U.S. EPA

James Morris, U.S. EPA Jeff Kelley, U.S. EPA

William Messenger, U.S. EPA Steve Ostrodka, U.S. EPA Scott Shane, Ohio EPA

Subject: Continuation of Removal Activities

Norwood Industries

1678 Norwood Ave., Toledo, OH

Latitude: 41.6553 Longitude: -83.5833

POLREP No.: 3 Site #: B5PA

Paranting Pariod: November 8 21 2008 D O #: 18

**Reporting Period:** November 8-21, 2008 **D.O. #:** 18 **Start Date:** 10/21/2008 **Response Authority:** CERCLA

Mob Date:10/16/2008Response Type:Time-CriticalCompletion Date:NPL Status:Non NPL

CERCLIS ID #: OHN000510295 Incident Category: Removal Action

RCRIS ID #: Contract # EPS60702

## **Site Description**

See POLREP #1 for a full Site Description

#### **Current Activities**

From November 8-21, 2008, EPA has completed the process of clearing the interior of the eastern and central portion of the warehouse facility by disposing of miscellaneous non-hazardous bulk debris. This is required to safely identify the presence of waste drums and containers that are intermingled with the general debris. EPA has utilized this space to stage drums and containers for Level B sampling activities. Currently, approximately 50% of the main building and all of the western portion of the warehouse is still inaccessible due to the haphazard accumulation of general debris.

To date, a total of 134 55-gallon drums and 253 5-gallon containers have been staged and sampled for Hazard Categorization (HazCAT) identification. Twenty-six (26) pallets

containing various solids (silica sands, finely milled sands, dyes, and powders) have been inventoried and disposed of in two (2) 20-cubic yard roll-off boxes. These powders were removed from the Site due to information gathered from Material Safety Data Sheets (MSDS) and off-site research. Thirteen (13) 20-cubic yard roll-off boxes of miscellaneous non-hazardous bulk debris have been removed from the Site, in addition to one (1) 20-cubic yard yard roll-off of RCRA empty drums.

START continues to monitor ambient air conditions both within and around the perimeter of the site for volatile organic compounds (with the AreaRAE system) and particulates (with a DataRAM and the Rapid Assessment Tools Software).

#### **Planned Removal Actions**

- Continue non-hazardous general debris removal and disposal;
- Continue segregation of materials;
- Continue sampling of all materials;
- Continue field Hazard Categorization (HazCat);
- Continue to develop waste streams;
- Perform final disposal; and
- Perform final building decontamination, if needed.

## **Next Steps**

Continue the Time-Critical Removal Action.

#### **Key Issues**

On November 18, 2008, an entry was made into the basement of the building, which was previously inaccessible due to the haphazard placement of general debris. During the investigation, an additional several hundred drums and small containers were discovered. In addition, at least three-quarters of the basement floor (which is the entire footprint of the main floor) is covered with an unknown liquid and sludge-like material. The source of the material on the floor is unknown and there are several floor drains. A pathway of cardboard boxes and burlap bags had been spread to provide access to all areas of the basement. At the back corner of the basement, there are burlap bags several feet thick laying on the floor and intermingled with the unknown sludge material. In addition, there is an elevator shaft that is approximately 4 feet deep with an oily liquid and the unknown sludge material from the floor. Samples have been collected for on-site HazCAT. An extensive inventory of the drums and small containers in the basement will be conducted to determine if additional funding will be required to complete the Removal Action.

#### Estimated Costs \*

	Budgeted	Total To Date	Remaining	% Remaining
Extramural Costs				
ERRS - Cleanup Contractor	\$200,000.00	\$157,000.00	\$43,000.00	21.50%

RST/START	\$25,000.00	\$23,000.00	\$2,000.00	8.00%
Intramural Costs				
USEPA - Direct (Region, HQ)	\$10,000.00	\$5,000.00	\$5,000.00	50.00%
Total Site Costs	\$235,000.00	\$185,000.00	\$50,000.00	21.28%

<sup>\*</sup> The above accounting of expenditures is an estimate based on figures known to the OSC at the time this report was written. The OSC does not necessarily receive specific figures on final payments made to any contractor(s). Other financial data which the OSC must rely upon may not be entirely up-to-date. The cost accounting provided in this report does not necessarily represent an exact monetary figure which the government may include in any claim for cost recovery.

## **Disposition of Wastes**

To date, removal of waste from interior of warehouse facility has consisted of non-hazardous misc. bulk debris classified as construction/demolition debris and non-hazardous inert solids. Thirteen (13) 20-cubic yard roll-off boxes of non-hazardous debris have been removed from the Site. In addition, two (2) non-hazardous inert solids roll-offs and one (1) 20-cubic yard roll-off of RCRA empty drums.

Waste Stream	Quantity	Manifest #	Disposal Facility
Construction/Demolition Debris	Estimated Weight 14 tons	11-05-08 Bill of Lading	Vienna Junction 6233 Hagman Road, Erie, MI 48133
Construction/Demolition Debris	Estimated Weight 14 tons	11-12-08 Bill of Lading	Vienna Junction 6233 Hagman Road, Erie, MI 48133
RCRA Empty Drums	Estimated Weight 20 cubic yards	0167917	Vienna Junction 6233 Hagman Road, Erie, MI 48133
Construction/Demolition Debris	Estimated Weight 14 tons	11-19-08 Bill of Lading	Vienna Junction 6233 Hagman Road, Erie, MI 48133
Non-Hazardous Inert Solids	Estimated Weight 20 Cubic Yards	0167913	Vienna Junction 6233 Hagman Road, Erie, MI 48133
Non-Hazardous Inert Solids	Estimated Weight 20 Cubic Yards	0167916	Vienna Junction 6233 Hagman Road, Erie, MI 48133

Construction/Demolition Debris	Estimated Weight 14 tons	11-21-08 Bill of Lading	Vienna Junction 6233 Hagman Road, Erie, MI
			48133

www.epaosc.net/Norwood